

Table of Contents

Chapter 1	
1.1 Introduction	2
1.2 Problem statement	2
1.3 Objectives	2
1.4 Scope	3
1.5 Methodology	3
Chapter 2	
2.1.1 Notable approaches to Quality Control	5
2.1.2 Total Quality Management	6
2.2 waste reduction	7
2.2.1 type of waste in manufacturing	7
2.3 Methodologies used in six sigma project (DMAIC)	8
2.3.1 Define phase of the project	8
2.3.2 Define Phase Deliverables phase of the project	9
2.3.3 Define Phase Topics	9
2.3.4 measure phase	10
2.3.5 Analysis phase	11
2.3.6 Improve phase	12
2.3.7 control phase	13
2.4 Seven Quality Tools	15
2.4.1. Parito Chart	15
2.4.2 cause and effect matrix (C&E)	16
2.4.3 Fishbone Diagram	16
2.5 Case study (Rubber gloves manufacturing processes)	16
2.5.1 Define phase of the project	17
2.5.2 Measure phase of the project	19
2.5.3 Analyze phase of the project	21
2.5.4 Improve phase of the project	22
2.5.5 Control phase of the project	24
2.5.6 Results, Discussion and Conclusions	24
Chapter 3	
3.1 PASEGIANOS	26
3.2 Polyethylene tetra phthalate line (PET)	26
3.3 Methodology	27
3.3.1 Define	27
3.3.1.1 Approval form content	30
3.3.4 Measure	33

3.3.2.1 Data collection plan	33
3.3.2.2 As-is Detail Process Map	33
3.3.2.3 The Cause and Effect (C&E) Matrix	34
3.3.2.4 Production and Waste	35
3.3.2.5 Filler data collection	36
3.3.3 Analyze phase	39
3.3.3.1 Fish bone diagram	39
3.3.4 Improve phase	41
3.3.4.1 QUALITY	41
3.3.5 Control phase	42
3.3.5.1 Control base line	42
Chapter 4	
4.1 Introduction	46
4.1.1 500 ml bottles cost and waste reduction project	46
4.1.1.1 Design of Measurement System of measure phase	52
4.2 Standardization	63
chapter 5	
5.1 Limitation	65
5.2 Conclusion	65
5.3 Recommendations	65
5.4 Reference	67

LIST of Table

Table 2.1 Notable approaches to Quality Control	5-6
Table 2.2 Defects reduction in rubber gloves	18-19
Table 2.3 result of case study	20
Table 2.4 result of case study	23
Table 3.1 production and waste per month	31
Table 3.2 approval form	32
Table 3.3 Ranking of causes	35
Table 3.4 Data form PASEGIANOS	37
Table 3.5 Data form FORAT Orange	38
Table 3.6 Data form ASEEL beer	39
Table 3.7 five whys list	41
Table 3.8 Action plane	42
Table 3.9 Control base line	42
Table 3.10 Quality and Waste rate before maintenance	43
Table 3.11 Quality and Waste rate after maintenance	44
Table 4.1 VOICE OF CUSTOMER	47
Table 4.2 Arriving at the Internal CTQ	49
Table 4.3 Project Plan	51
Table 4.4 Operational Definition of Y(s)	52
Table 4.5 Cause and Effect Matrix of measure phase	54-55
Table 4.6 Data Collection Plan of measure phase	55-56
Table 4.7 Target Setting Defect per million (DPM)	58
Table 4.8 Potential of Vital Causes	60
Table 4.9 Action Plan	62

List Of Figure

Fig 2.1 Seven Quality Control tools	15
Fig 2.2 Fishbone Diagram	16
Fig 2.3 Case study (Rubber gloves manufacturing processes)	17
Fig 2.4 Case study Gloves defects Pareto chart	20
Fig 2.5 Gloves manufacturing process flowchart	21
Fig 2.6 Cause-and-effect diagram related to the leaking gloves quality problem	22
Fig 2.7 defects by oven temperature and conveyors speed	22
Fig 2.8 states of conducting the Six Sigma project in the gloves manufacturing process	24
Fig 3.1 Main Process of PET line	27
Fig 3.2 PET Utilization / L (%)	28
Fig 3.3 pareto chart for waste of machines	29
Fig 3.4 in Detail pareto chart for waste of machines	29
Fig 3.5 Waste of Production Lines in 2014	36
Fig 3.6 Constructing a Fishbone Diagram	40
Fig 4.1 Arriving at the Project CTQ waste of bottles /product	47
Fig 4.2 total empty bottles waste	48
Fig 4.3 Defining a project	50
Fig 4.4 Supplier inputs process outputs customers (SIPOC)	50
Fig 4.5 As-is Micro-Level Process Map	53
Fig 4.6 As-is Detail-Level Process Map	53
Fig 4.7 product 1 Measurement System Analysis	56
Fig 4.8 product 2 Measurement System Analysis	57
Fig 4.9 product 3 Measurement System Analysis	57
Fig 4.10 Cause Analysis	59
Fig 4.11 five whys	61
Fig 4.12 control base line before maintenance	63
Fig 4.13 control base line after maintenance	63