

Table (B)
Relationship between processes and percentage of waste (2004-2003)

2004 First quarter							
Processes	Drawing	Cutting	Pointing	Lead core	Assembling	Grooving	control
Percentage of waste%	0.04	0.10	0.06	0.57	1.96	0.00	0.00
2004 Second quarter							
Processes	Drawing	Cutting	Pointing	Lead core	Assembling	Grooving	control
Percentage of waste%	0.02	0.04	0.02	0.23	1.73	0.00	0.00
2004 Third quarter							
Processes	Drawing	Cutting	Pointing	Lead core	Assembling	Grooving	control
Percentage of waste%	0.03	0.06	0.04	0.05	1.80	0.00	0.00
2004 Fourth quarter							
Processes	Drawing	Cutting	Pointing	Lead core	Assembling	Grooving	control
Percentage of waste%	0.06	0.08	0.06	0.50	2.39	0.00	0.00
2003 First quarter							
Processes	Drawing	Cutting	Pointing	Lead core	Assembling	Grooving	control
Percentage of waste%	0.00	0.00	0.00	0.01	0.03	0.00	0.00
2003 Second quarter							
Processes	Drawing	Cutting	Pointing	Lead core	Assembling	Grooving	control
Percentage of waste%	0.00	0.00	0.00	0.01	0.03	0.00	0.00
2003 Third quarter							
Processes	Drawing	Cutting	Pointing	Lead core	Assembling	Grooving	control
Percentage of waste%	0.00	0.00	0.00	0.01	0.03	0.00	0.00
2003 Fourth quarter							
Processes	Drawing	Cutting	Pointing	Lead core	Assembling	Grooving	control
Percentage of waste%	0.07	0.14	0.07	1.44	3.12	0.00	0.00
2003 Half year							
Processes	Drawing	Cutting	Pointing	Lead core	Assembling	Grooving	control
Percentage of waste%	0.00	0.00	0.00	0.01	0.03	0.00	0.00
2003 Year							
Processes	Drawing	Cutting	Pointing	Lead core	Assembling	Grooving	control
Percentage of waste%	0.04	0.09	0.12	1.16	3.07	0.00	0.01