

# *Dedication*

To:

My little family  
My comming baby  
Dears ....  
Father ..  
Mother ..

*Wiam*

# Acknowledgement

Let me express the unlimited gratitude and appreciation to my supervisor Dr. Jumma Yousif Tamboul for his sincere supervision.

Thanks extended, also to the staff of Sudan atomic energy commission, especially radiation protection and environmental monitoring department staff for their great help to fulfil this study. Also appreciation is to the staff of the x-ray department in omdurman children hospital and to them, who helped and supported.

# Abstract

A practical study was conducted about the importance of quality assurance in pediatric radiology in Omdurman pediatric hospital. The objectives of the study were to assess the performance and efficiency of the x-ray department in Omdurman pediatrics emergency hospital. In term of improvement to the image quality, save time and low cost. Relevant data were collected and obtained by observation, practical measurements, Interviews, Reject film analysis and quality control tests in order to achieve the above mentioned objectives.

The study revealed that there are no radiation protection tools for technologists, patients and co-patients in the x-ray department. No immobilization tools and high overall reject rate (8.5 %). The quality control tests illustrate that the x-ray machine needs calibration and the dark room is not ideal.

The study recommended that the control unit should be separated from the dark room. Light leakage to x-ray films in the dark room through the door should be treated. The x-ray department should be supplied with radiation protection and immobilization tools, that is to ensure low cost, save time and image quality.

# ملخص الدراسة

اجريت الدراسة العملية لتوضيح أهمية ضبط الجودة في قسم الأشعة التشخيصية بمستشفى حوادث الأطفال - أمدرمان. أهداف هذه الدراسة تقييم أداء وكفاءة قسم الأشعة التشخيصية بمستشفى حوادث الأطفال - أمدرمان. وذلك لتحسين جودة الصور وتوفير الوقت وتقليل التكلفة. تم جمع البيانات عن طريق الملاحظة والمقابلة الشخصية والقياسات العملية وتحليل الأفلام التالفة وإختبارات ضبط الجودة للوصول إلى الأهداف أعلاه.

أوضحت الدراسة عدم وجود أدوات الوقاية من الإشعاع للعاملين والممرضى والمرافقين في قسم الأشعة التشخيصية. عدم وجود أدوات التثبيت ونسبة عالية من الأفلام التالفة (٨٠٪). أوضحت الدراسة أن جهاز الأشعة يحتاج إلى تقييس والغرفة المظلمة غير مناسبة.

أوصت الدراسة بضرورة فصل وحدة التحكم عن الغرفة المظلمة ومعالجة تسرب الضوء إلى الأفلام عن طريق باب الغرفة المظلمة. يجب أن يزود قسم الأشعة بأدوات الوقاية من الأشعة وأدوات التثبيت وذلك لتأكيد تكلفة منخفضة وتوفير الزمن وتحسين نوعية الصورة.

## Tales of contents

Dedication .....	I
Acknowledgement .....	II
Abstract (English) .....	III
Abstract (Arabic) .....	IV
Tables of contents .....	V
List of figures .....	VII
List of tables .....	VIII
List of abbreviations .....	IX

# **Chapter one**

## **General Introduction**

.....	1.1 Problem of the study	1
.....	Hypothesis 1.2	2
.....	Objectives 1.3	2
.....	Methodology 1.4	2
.....	Thesis Scope 1.5	3

# **Chapter two**

## **Literature review**

2.1 Ideal pediatric x-ray department .....	4
2.1.1 X-ray room .....	4
2.1.2 Waiting room .....	5
2.1.3 Dark Room .....	5
2.2 Radiation protection in children .....	6
2.2.1 Radiation protection devices .....	7
2.3 Immobilization .....	9
2.3.1 Type of available immobilization tools .....	10
2.3.2 Immobilization devices classification .....	11
2.3.2.1 Immobilization board .....	11
2.3.2.2 Chest chair .....	13
2.4 Quality Assurance .....	14
2.4.1 Definition .....	14
2.4.2 Aim of quality assurance.....	14
2.4.3 Radiology Department QA Committee .....	14
2.4.4 Radiology Department QA Program .....	15
2.4.5 The framework of QA program .....	15
2.5 Quality control (QC) .....	17
2.5.1 Definition .....	17
2.5.2 Aim of quality control program .....	17
2.5.3 QC Technologist .....	17
2.5.4 Types of Quality control test .....	17
2.5.5 Quality control program .....	18
2.5.6 Quality control program for radiological department ..	18
2.5.6.1 Visual inspection .....	18
2.5.6.2 Environmental inspection .....	18
2.5.6.3 Performance test .....	19
2.5.7 Parameters to be checked .....	19
2.6 Reject analysis .....	19
2.6.1 Definitions .....	19

2.6.2 Aim of reject analysis .....	20
2.6.3 Departmental record .....	20
2.6.4 Reject rates .....	21
2.6.5 Reject sheets .....	22

## **Chapter three**

### **Practical work and results**

3.1 X-ray department construction .....	25
3.2 Quality control tests .....	27
3.2.1. KVp and time accuracy .....	27
3.2.2 Relative mA and mAs linearity .....	28
3.2.3 mAs consistency .....	29
3.2.4 KVp and time reproducibility test .....	30
3.2.5 HVL (Half Value Layer) .....	31
3.2.6 Radiation filed .....	33
(A) Collimator tests .....	33
(B) Beam Alignment .....	33
(I) Perpendicularity test .....	34
(II) Coinciding test .....	35
3.2.7 Assessment of Focal Spot size .....	36
3.3 Reject analysis .....	38

## **Chapter four**

### **Discussion, conclusion and recommendation**

4.1 Discussion .....	41
4.2 Conclusion .....	42
4.3 Recommendations .....	43

## **References and appendix**

References .....	
Appendix .....	

---

## **List of figures**

---

Figure 2.1 Gonadal shield template showing the base extended to absorb scatter radiation from the edge of the filed .....	8
--	---

Figure 2.2	
The dimension of the immobilization board .....	11
Figure 2.3	
Infant immobilized on immobilization board using straps .....	12
Figure 2.4	
Infant and toddler in chest chair .....	13
Figure 2.3	
Basic component and operational framework for QA program .....	16
figure 3.1	
The construction of the x-ray department in Omdurman emergency pediatric hospital .....	26
Figure 3.2	
Digital KVp meter .....	27
Figure 3.3	
Digital KVp meter used for measurement of kVp .....	27
Figure 3.4	
Assessment of filtration (HVL) procedure .....	31
Figure 3.5	
Radiation intensity versus attenuator thickness for determination of half-value layer .....	32
Figure 3.6	
Beam alignment and collimator test tool .....	34
Figure 3.7	
Result film of beam alignment and perpendicularity test .....	35
Figure 3.8	
Focal spot test tool .....	36
Figure 3.9	
Procedure of focal spot size assessment .....	36

---

## **List of tables**

Table 2.1	
Sizes of female gonadal shielding according to ages.....	8
Table 2.2	

Sample reject sheet .....	23
Table 2.3	
Reject Analysis - Coded Reject Sheet .....	24
Table 3.1	
KVp and time accuracy factors and calculations .....	28
Table 3.2	
Relative mA and mAs linearity .....	29
Table 3.3	
mAs consistency factors .....	30
Table 3.4	
Factors for KVp and time reproducibility test .....	30
.....	
Table 3.5	
Half value layer (HVL) .....	32
Table 3.6	
Recommended minimum HVL at various KVp values .....	33
Table 3.7	
The factors that must be checked in the collimator .....	33
Table 3.8	
Perpendicularity test results .....	34
Table 3.9	
Coinciding test results .....	35
Table 3.10	
Focal spot size test results .....	37
Table 3.11	
Effective focal spot size for magnification of 4/3 .....	37
Table 3.12	
Accepted error for Assessment of Focal Spot size .....	38

---

## **List of abbreviations**

---

Kvp :Kilo voltage peak  
 mA :Milli ampere

mAs	:Milli ampere second
AP	:Antreo-posterior
PA	:Postero-anterior
FFD	:Focal film distance
HVL	:Half Value Layer
QC	:Quality control
QCP	:Quality control program
QA	:Quality Assurance
QAP	:Quality assurance program
QAC	:Quality assurance Committee
T	:Time
LBD	:Light beam diaphragm